RAZORGAGE
POSITIONERS • SOFTWARE • SYSTEMS

Turn Off Pockethole Drilling or Scribing

Step 1

From the MAIN SCREEN click MORE.

Step 2

Then click STARTUP SETTINGS

Step 2

Here you can turn on / off secondary operations.

Razor Optimal (v3.3.17) Serial Number:

PARTS LIST	
LABELS	
DIAGNOSTICS	
VIEW CUT PARTS	
MORE	
PURGE PRINTER	
EXIT	

OTHER OPERATIONS

Parameters for machine operation	Parameters
Labels Displayed	Display Labels
Define how parts are grouped	Part Grouping
Units for Display of Total, Short, Long	Sum Units
Enter or select operator, supplier	Operator/Supplier
Set Part Units: Inches or mm	Units
Cut from Parts List or Defect Removal	Op Mode
View Encoder Type	Encoder
View/Change the Stroke, Home Side	Setup
Ports, Defect Method, Ink Jet, Accessories	Startup Settings

...TION SELECTION

Load Saved Settings

M-Drive

M-Drive Serial Port [cmboP▼] Find

PLC Serial Port

PLC Serial Port [cmboP▼] Find

Defecting Method

○ Crayon
○ Joy Stick   ☐ Has Gripper
○ .....

Crayon Scanner Port [cmboP▼] Find

Printer

☐ Has an Ink Jet Printer

Ink Jet Serial Port [cmboP▼] Find

RazArray

☐ Has RazArray 1 (1-64)

RazArray 1 Serial Port [cmboP▼] Find

☐ Has RazArray 2 (65-128)

Raz Array 2 Serial Port [cmboP▼] Find

Accessories

☐ Scribing
☐ Space Balls
☐ Pocket Holes

If settings are changed, you must exit and re-start the software.

Save Settings   Cancel